

P2

# Center motor & carrier 6 battery

28", 36V, center display, torque sensor & f/coaster brake

- Superior driving experience
- Reduced noise
- Added functionalities in displays and motors
- UART communication
- Battery capacity 7,8 AH - 17,4 AH\*
- Real time information
- EMC tested according to EN15194

VS 2



Carrier 6 battery\*



Carrier 6




Center display w/throttle Ø22



Wheel speed sensor for center motor



Center motor, torque sensor and f/coaster brake.  
50378-38. Standard chainwheel for internal hub.



## Predefined e-kit solutions (60260)

		Part no.
<b>Motor</b>	Center motor, 250W	50371
<b>Sensor</b>	Wheel speed sensor for center motor	50374
<b>Mounting kit</b>	Accessories for centermotor	

		Part no.
<b>Display</b>	Center w/throttle & handlebar Ø22	50935
<b>Carrier</b>	Carrier 6	60018
<b>Battery</b>	Carrier 6	

Incl. all necessary parts for mounting.  
\*Battery not included - various capacities are available.

Options on the next page

# Center motor & carrier battery

28", 36V, center display, torque sensor & f/coaster brake

OPTIONS			
<b>Motor</b>	Center motor with torque sensor, f/freewheel	<b>1</b>	
<b>Chainwheel</b>	42T or 46T		
<b>Shiftsensor</b>	Shift sensor for center motor /int. gear	<b>2</b>	
<b>Display</b>	Minimal LCD / LED	<b>3</b>	Slim display LCD / LED <b>4</b>
<b>Bracket for center display</b>	Ø25,4 or Ø32		
<b>Light</b>	Wire for light		Front lamp + wire

STANDARD WIRE LENGTHS			
	Extension wire from motor	Components	Total
<b>Shift sensor</b>	700 mm	700 mm	1400 mm
<b>Light</b>	700 mm		700 mm
<b>Display</b>	700 mm	600/800 mm	1300/1500 mm
<b>Motor:</b>			
<b>Battery connection</b>		680 mm	680 mm
<b>Wheel speed sensor</b>		220 mm	220 mm
<b>Connection for extension wire</b>		130 mm	130 mm



- Slim display LCD/LED are all available with buttons or throttle.
- For suitable frames see our frame catalog.

*Have in mind that non-predefined options are special orders, expect longer delivery time and a minimum quantity.*

OPTIONS




Center motor with torque sensor, f/freewheel (50361)



Shift sensor for centermotor / int. gear (50373)



Minimal display LCD / LED (50707-2 / 50706)



Slim display LCD / LED (50946 / 50947 w/buttons 50943 / 50944 w/throttle)